

Oil Field Environmental Incident Summary

Incident: 20160103195851 **Date/Time of Notice:** 01/03/2016 19:58

Responsible Party: Enable Midstream

Well Operator: XTO ENERGY INC.

Well Name: HM HOVE 34X-33 CENTRAL TANK BATTERY

Field Name: WEST CAPA

Well File #:

Date Incident: 1/3/2016 **Time Incident:** 09:00 **Facility ID Number:** 218102-01

County: WILLIAMS **Twp:** 155 **Rng:** 96 **Sec:** 33 **Qtr:** SW SE

Location Description: LAT: 48.19811 LONG: -103.03104

Submitted By: John Launius

Received By:

Contact Person: John Launius
P.O Box 6501
Englewood, CO 80155

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.1 Mile

Distance Nearest Water Well: 0.1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	4	Barrels	4	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/5/2016

Clean Up Concluded: 1/26/2016

Risk Evaluation:

Low impact. Ground is frozen and material is contained on site. All standing liquids have been recovered.

Areal Extent:

60 feet X 80 feet with a soil depth impact of 1 to 2 inches.

Potential Environmental Impacts:

Minor environmental impact. All standing liquids have been recovered. Once the one-call has cleared the impacted soil will be excavated and disposed of properly.

Action Taken or Planned:

The Emergency Response contractor has removed all free standing liquids. The unit has been shut in and will remain out of service until all environmental cleanup activities have been completed and the unit has been thoroughly checked out. Approx. 4 bbl of crude oil was recovered along with approx. 6 bbl of snow melt, soil and gravel were recovered.

Wastes Disposal Location: Chimney Butte Landfill, 1217 Highway 85, Fairfield, ND 58627, (877) 827-0851

Agencies Involved:**Updates**

Date: 1/4/2016 **Status:** Reviewed - Assigned to Other Agency **Author:** Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC has oversight.